



Grid Solutions



Multilin

Replacement Parts & Accessories

369 - Motor Protection System - Parts



12 POS Phoenix Connector

Part Number: **0606-0113**

16 POS Phoenix Connector (90 Degrees)

Part Number: **0606-0112**

15' 369 RJ-45 Cable (Remote Faceplate Cable)

Part Number: **0804-0133**

3.5" 369 RJ-45 Cable

Part Number: **0804-0134**

269Plus to 369 Drawout Upgrade

Key Features

- Seamless upgrade for existing Drawout Multilin 269 Motor Management Relays
- Reduce system downtime utilizing the existing Multilin 269 Motor Management Relay drawout chassis
- Reduce maintenance & operational costs - eliminates the need for mounting kits, re-work to existing cutouts and re-wiring of the chassis
- Upgrade with ease using automated setting file conversion tool
- Take advantage of newer, more advanced hardware and feature set

